

Tuesday, March 29, 2022 Licence/Permit Number: 602642 **Date of Inspection:**

Licensee/Permittee Name: THE CORPORATION OF THE TOWNSHIP OF ZORRA

Site Name: ROBINSON PIT

Address: 274620 27TH LINE P.O. BOX 306,

INGERSOLL

E-Mail Address: soliver@zorra.on.ca

PT OF LOT Lot(s):

29

Conc.(s):

Township: ZORRA

Local Municipality:

ZORRA TP

Mining Claim #:

County/Region:

OXFORD CO

UTM# (NAD 83): Extraction Area (ha):

18.92

Licence/Permit Area (ha): 37.03 **Inspection Category:**

Follow-up

Authority Type:

Class A Licence

Operation Type:

Pit

Operating Status:

Dormant

Above Water:

Yes

Critical Inspection Items

Inspection Results: ✓ Compli	ance X Non Compliance	n/a Not applicable n/i Not Inspected		
A. General				
1. n/i Identification Sign	2. ^{n/i} Gates	3. n/i Entrance/Exit:		
B. Operational				
1. ^{n/i} Berms	2. n/i Setbacks	3. n/i Stockpile Location		
4. n/i Face Heights	5. n/i Trees within 5m	6. n/i Extraction Depth		
7. ^{n/i} Buildings	8. ^{n/i} Stripping	9. ^{n/i} Progressive Rehab		
10. n/i Inert Fill	11. n/i Undercutting	12. n/i GPS Corners		
13. n/i Boundary Demarcation				
C. Equipment				
1. ^{n/i} Asphalt Plant	2. n/i Concrete Plant	3. n/i Portable Crusher		
4. n/i Permanent Crusher	5. ^{n/i} Wash Plant	6. n/i Screening Plant		
D. Environmental				
1. ^{n/i} Pumping	2. ^{n/i} Discharging (ECA)	3. ^{n/i} Ditching		
 n/i Permit to take Water 	5. ^{n/i} ECA 3	6. ^{n/i} Scrap		
7. n/i Dust	8. ^{n/i} Fuel Storage	9. ^{n/i} ESA		
10. ^{n/i} PSW	11. ^{n/i} Woodlands	12. ^{n/i} ANSI		
E. Recycling				
1. ^{n/i} Asphalt (RAP)	2. n/i Concrete	3. n/i Glass		
4. ^{n/i} Bricks	5. ^{n/i} Slag	6. ^{n/i} Asphalt Shingles		
F. Monitoring Reports				
1. ^{n/i} Water Monitoring	2. ^{n/i} Noise Monitoring	3. n/i Blast Monitoring		
4. ^{n/i} AMP				
G. Other / Notes				

(---1---) This inspection was a follow-up to ones that occurred October 29, 2021, November 9, 2021 and October 22, 2019. All remedial action called for by the earlier reports have been completed – thank-you! (---2---) The west 10 metre setback adjacent to woodlot 1b has been marked with a series of t-bar stakes and 12 Red Oak and 8 Spruce trees, of variable heights between one foot to four foot tall, were observed planted in the setback. (---3---) You are encouraged to maintain the plantings in the setback areas as they could be the source of trees or tree seed needed for the proposed planting or natural regeneration of side slopes.

Inspection Results

Satisfactory (Site in Compliance): Yes	
Remedial Action Required by Licensee/Permittee: No	

Delivery/Attachments/Referral

	50	. y// kttaommomo/rk	olonial
Delivered By:	Mail:	EMail:	Personal:
Discussed/Accompa	anied by: n/a		
Referred To:	Ministry of the Enviro	nment and Climate Ch	nange:
	Ministry of Labour:		
	Fisheries and Oceans	s Canada:	
	Ministry of Northern D	Development and Mine	es:
	Other:		
Reason for referral:			

Aggregate Inspector Information

Badge #: 046 **Name:** Stephen Douglas **Phone:** 548-388-8047 **Fax:** 519-773-9014

Address: 615 John Street North, Aylmer, Ontario N5H 2S8

E-Mail: stephen.douglas@ontario.ca MNR District: Aylmer

Inspection Photos



2022/03/29 13:09:53
TG-4 - P3290318.JPEG
Taken by: Stephen Douglas
View N along the ten metre setback to the W
of woodlot 1b. The setback is well-marked with
t--bar stakes



2022/03/29 13:10:11 TG-4 - P3290319.JPEG Taken by: Stephen Douglas Spruce tree in setback



2022/03/29 13:10:33 TG-4 - P3290320.JPEG Taken by: Stephen Douglas Red Oak tree marked with 2-foot tall stake



2022/03/29 13:12:33 TG-4 - P3290321.JPEG Taken by: Stephen Douglas View S along the ten metre setback to the W of woodlot 1b. Some tree plantings can be observed.